Volkswagen Tiguan 1.5 110kW

ID: 10710164

Car's location:	**Latvia**	Displacement:	**1500cm³**
Dealer:	**Moller Auto Rīga**	Power:	**150 hp (110 kw)**
VIN code:	**WVGZZZCT4RW015856**	Drivetrain:	**front**
License plate:	**NV2555**	Gearbox:	**Automatic**
First registered:	**04/2024**	Fuel:	**gasoline**
Mileage:	**92540km**	Doors :	**4/5 doors**
Technical inspection:	**04/2028**	Color:	**blue**



Møller Auto Rīga

K. Ulmaņa gatve 115, Mārupe

riga@moller.lv

+371 67097107

Gearbox

- Automatic

Safety and security

- Electromechanical power steering
- ABS brakes
- ESP stability control
- ESC stability control
- EDS/ASR traction control
- Electromechanical parking brake
- Auto hold function
- Third brake light
- Fullsize airbags
- Head airbags
- Knee airbag
- Seat belts in front with tensioners
- Isofix child seat mounting
- Central locking
- Anti-theft alarm system
- Rain sensor
- Side airbag

Assistant systems

- Adaptive cruise control
- Speed limiter
- Forward Collision Warning "Front Assist"
- Lane change assistant "Side Assist"
- Heading control "Lane Assist"
- "Emergency Assist"
- Dynamic Road Sign Display
- Parking sensors in front and rear
- Digital driver display

Tyres and wheels

- Light alloy wheels
- Summer tires

Lights

- Fog lights front
- Fog lights rear
- Separate daytime running lights
- LED headlights
- LED rear lights
- automatic headlight-range adjustment

Multimedia

- Radio
- Touch-screen
- AUX-IN jack
- Navigation system
- Bluetooth interface
- Mobile phone interface
- App Connect
- Multi-function color display
- Active Info Display
- Driver information system
- USB-C input

Seats

- Textile seats
- Leather seats
- Heated seats in front
- Folding rear seat backrest
- Front armrest
- Rear armrest

Interior/comfort

- Leather steering wheel
- Adjustable steering wheel
- Cup holders
- Electrical windows in front and rear
- Tinted windows
- Electrical tailgate opening
- Electrically adjustable mirrors
- Heated mirrors
- Folding mirrors
- Heated steering wheel
- Insulated glass

Heating/climatisation

- Interior heating system
- Air conditioning system
- Automatic Air Care "Climatronic" 3 zone

Other Equipment

- Roof railings
- Service book
- Extended warranty


Moller Auto

Moller Auto

Moller Auto

Moller Auto

Moller Auto









11:18
Palīgsistēmas
Lane Assist
Side Assist
READY




11:18
Stūres rata apsilde ir ieslēgta.
READY






















